
Earth pipe exploded view: pipe, lug and weld

Galvanised earth pipe parts and manufacturing sequence, with the conductor-to-lug connection kit


GALVANIZED & STAINLESS EARTH PIPE · HGV · HSL · HSM 3 / 6 · 3"

KALOT GROUP · TECHNICAL ILLUSTRATION · NOT TO SCALE

Conductor-to-lug connection kit



Galvanised earth pipe parts



Cutting and preparation 1
3 or 6 m pipe and 200 × 40 × 10 strip with two holes

Positioning the lug 2
Outside the pipe top, flush against the wall, with 50 mm overlap

Welding 3
Fillet weld around the lug and pipe overlap

Hot-dip galvanising 4
Zinc coating on pipe, lug and weld, after welding

Figures are illustrative and not to scale; dimensions in mm; tighten bolts to the manufacturer's instructions.
We keep improving our products; please confirm final dimensions with our experts.

KALOT GROUP
KALOT Group
Protect Today For Tomorrow
www.kalot.ir
Tel +98 21 2268 8852