
Two-bolt parallel clamp connection modes

Top view, not to scale

PCC


KALOT GROUP · TECHNICAL ILLUSTRATION · NOT TO SCALE

3. Two parallel through-run conductors




Both conductors run through the clamp and are joined at this point.

2. In-line joint of two conductors



The two conductor ends sit side by side in the two grooves, facing opposite ways, and protrude slightly from the clamp.

1. Branch from main conductor



The main conductor runs through the clamp; the branch conductor is clamped in the second groove and leaves the clamp.

Views are from above the clamp; its two grooves lie either side of the bolts. Both conductors' cross-sections must fall within the range of the same code.

This document is not contractual; we may update product design, dimensions, weights and images without prior notice.

گروه کالوت
KALOT GROUP
Protect Today For Tomorrow
Since: 1972 تاسیس: ۱۳۵۱
www.kalot.ir · Tel +98 21 2268 8852